


1

MY
HOUSE

S Scottish Dr

E Marthas Cv

E Marthas Cv



2

S Scottish Dr

E Marthas Cv

(1 of 3)

Cleanout:

SD_Identif	
Date_Creat	8/7/2013 6:00 PM
Depth_From	4.60
Pipe_Diam	9
Connection	Yes
C1_Size	15
C1_Type	CPP
C1_Dirch	South
C1_Depth	4.60
Connectio2	Yes
C2_Size	15
C2_Type	RCP

[Zoom to](#)

E Marthas Cv

3

S Scottish Dr

E Marthas Cv

E Marthas Cv

(1 of 3)

Attribute

C4_D_rect

C4_Depth 2.25

Maintenance Yes

Maintenance tree growing over lid

Cleaned No

Date_E_En

Buried_Man No

Surface_Ty

Other_Surf

General_Co

ObjectID {34EC6B13-A1A4-4E7F-8340-659F6DBCD343}

PID 0

[Zoom to](#)

4

Water pooled here, then drained
Into my yard, overwhelming my
Sump drainage system, breaking
Two windows and depositing 33,000
Gallons of mud and water into
My basement.

This is a zoomed-in version showing
the cleanout should be right behind
the pre-existing fence that was in
place when we bought the lot.
The cleanout is no longer there, or
It has been buried. On Tuesday,
September 17th, two men from
Gilson Engineering were out looking
For the missing cleanout. they did
Not find it.