


# 500 East Resurfacing

May 13, 2020




# Existing Cross-Section




# Survey Results

- 122 Responses
- Major Takeaways:
  - Lack of Bike Facilities
  - Concerns about Speeding, Missing Sidewalks/Crosswalks
  - Concerns about road surface conditions
  - Concerns about lack of traffic control measures




# Initial Design Configuration




# What We Heard Back


- Concerns about lack of SB Bike Lane
- Concerns about the 12' lane and speeding
- Concerns about pedestrian crossings and facilities



# What SB Bike Lane would look like



# Updated Design Configuration



# Next Steps

- Interested in hearing this groups feedback on our updated design
- Will be attending BAC next Monday to also receive feedback
- Hoping to finalize this next week if possible based on that feedback
- The resurfacing is now scheduled for the latter half of July (subject to change)
- Continuing to receive comment at [streetresurfacing@slcgov.com](mailto:streetresurfacing@slcgov.com)