

QUOTE

Mt. Talau Concrete

Ringo Pulini
(425) 589-7812
13027 S Chandler Boy Ct. Riverton UT, 84065

6/6/2022

100-3

Pearson

JOB

PAYMENT TERMS

Sidewalk and Street Entrances for Main Street & 500 S

Quote includes replacement of:

*Sidewalk on Main Street (ex. immediately in front of the
Hotel and the Restaurant)*

4 Street Entrances to be replaced

Curb and Gutter

**Mow Strip on Main Street (inc. in front of Diner and
Hotel)**

Mow Strip on 500 S

DESCRIPTION	Column1	Amount	ement Cost	Labor Cost
3 Street Entrances on Main Street to be replaced Sidewalk on Main Street (exl. immediately in front of the Hotel and the Restaurant) Curb and Gutter	Cement Costs	22 yd	\$4,316.00	\$11,443.74
Middle Entrance taken out on 500 S	Cement Costs	2 yd	\$392.00	\$1,040.34
2 Entrances on 500 S Replaced	Cement Costs	3 yd	\$588.00	\$1,560.51
Mow Strip on 500 S	Cement Costs	12 yd	\$2,352.00	\$6,242.04
Mow Strip on Main Street (incl. in front of Diner and Hotel)	Cement Costs	21yd	\$4,116.00	\$10,923.57
Base Gravel	Gravel Costs	2 Tons	\$100.00	
Rebar for Entrances	Rebar Costs		\$126.00	

**Labor costs based on \$520.17/yd (inc. ripout and install)*

**Pricing is based on City Mix of Cement at \$196/yd*

	60 yd	\$11,990.00	\$31,210.20
TOTAL LABOR & CEMENT			\$43,200.20

Make all checks Payable to Mt. Talau Concrete

13027 S Chandler Boy Ct. Riverton UT, 84065 (425) 589-7812

