

## 700 South Well Repair & Transformer Upgrade

Transformer Upgrade	\$85,000 (in budget)
Repair Pole Fire – Rocky Mountain Power	\$ 7,000 (paid from transformer fund)
Electrical Trouble Shooting	\$ 5,000 (paid from transformer fund)
700 South Pump Motor Removal	\$10,000 (paid from transformer fund)
Motor Shipping & Evaluation	\$ 8,000
New Pump Motor	\$97,000
Motor Installation	\$15,000
Bidding and Contingency	\$33,000
Additional Funding	\$175,000