#	Tier I	Construction Date
1	North I-80 Rest Area	ca. 1960
2	494 E. Chalk Creek Rd.	ca. 1880
3	200 N. East Henefer Rd.	ca. 1890
4	81 S. Main St., Henefer	ca. 1880
5	Pinecliff Camp Lodge, 4142 E. Chalk Creek Rd.	ca. 1890
	Tier II	**Construction Date**
6	670 N. Main St., Coalville	ca. 1925
7	3320 E. Chalk Creek Rd., Upton	ca. 1930
8	2325 N. West Henefer Rd.	ca. 1945
9	391 E. Chalk Creek Rd., Coalville	ca. 1960
10	831 S. Hoytsville Rd., Hoytsville	ca. 1885
	Tier III	**Construction Date**
11	215 N. Main St., Henefer	ca. 1890
12	20 S. Main St., Henefer	ca. 1900
13	516 E. Chalk Creek Rd.	ca. 1900
14	1085 S. West Hoytsville Rd., Hoytsville	ca. 1905
15	1090 S. West Hoytsville Rd., Hoytsville	ca. 1905

Dropbox link: https://www.dropbox.com/scl/fo/mpfe25oil1fvgb77f41z1/AMMcMiWYhMHx

Type
Public
Residential
Residential
Residential
Recreation

Type
Residential
Barn
Barn
Residential
Residential

Type
Residential
Residential
Residential
Residential
Residential

:F1Jb9lkvdps?rlke

Notes
Unique design with high integrity on exterior and interior; historic landscape consideration with s
Started as a Central passage house; expanded with Crosswing to the rear; substantial size and
High style Victorian-era house with high integrity; outside town boundary
Substantial size; brick construction; Central passage/Double pile form; high integrity
Former dance hall; board form concrete construction; rare use statewide and in county
Crosswing form with unique flared roof design and substantial dormers; fine Classical detailing;
When compared with other wood barns, this is unique in size and integrity; could be prominent f
Substantial size; example of a barn from a later period; concrete block construction with barrel-v
Rare example of mid-century architecture in this part of the county; likely architect-designed
Appears to be a Crosswing with Victorian detailing and high integrity, including some original wir
Center Crosswing example with a few Victorian details; garage addition
Two-story example of a Crosswing and location on Main Street; good integrity
Crosswing form with Victorian era details; poor condition (may be vacant)
May be an important intersection; Victorian form with fine sandstone construction
May be an important intersection; Sandstone construction

ey=2ay40w2h7bfsjtu01yg7obif0&dl=0

Current Owner
UDOT Don Donaldson Craig Saxton Wade Kellems United Methodist Church
Joann Rees Jones Pineview Ranch Linda J Roberts Trustee Bradley Vernon Ike Edgel
Angela Lindley Robert Skinner Denny Wright Michael Hays Dale Wilkinson