



## BOUNTIFUL COLLISION CENTER

730 WEST 500 SOUTH, WEST BOUNTIFUL, UT  
84087  
Phone: (801) 397-3733

Workfile ID: fd1c1f01  
Federal ID: 90-0006916  
State ID: Utah  
Resale Number: 12542215-002-STC  
Federal EPA: NA  
State EPA: NA

### Preliminary Estimate

**Customer: SLC Mosquito Abatement**

**Job Number:**

Written By: Ryan Gee

Insured: SLC Mosquito Abatement  
Type of Loss:  
Point of Impact: 05 Right Rear

Policy #:  
Date of Loss:

Claim #: FLEET  
Days to Repair: 0

**Owner:**  
SLC Mosquito Abatement  
(801) 433-7797 Business

**Inspection Location:**  
BOUNTIFUL COLLISION CENTER  
730 WEST 500 SOUTH  
WEST BOUNTIFUL, UT 84087  
Repair Facility  
(801) 397-3733 Day

**Insurance Company:**

### VEHICLE

2011 CHEV Silverado 2500 HD Work Truck Regular Cab 133.7" WB 4WD 2D P/U 8-6.0L Gasoline SFI White

VIN: 1GC0KVCG0BF160380  
License: 508831EX  
State: UT

Interior Color:  
Exterior Color: White  
Production Date: 11/2010

Mileage In:  
Mileage Out:  
Condition:  
Vehicle Out:  
Job #:

#### TRANSMISSION

Automatic Transmission  
Overdrive  
4 Wheel Drive

#### POWER

Power Steering  
Power Brakes

#### DECOR

Dual Mirrors

#### CONVENIENCE

Air Conditioning  
Intermittent Wipers  
Tilt Wheel  
Message Center  
Climate Control

#### RADIO

AM Radio  
FM Radio

Stereo

Search/Seek

#### SAFETY

Drivers Side Air Bag  
Passenger Air Bag  
Anti-Lock Brakes (4)  
4 Wheel Disc Brakes  
Traction Control  
Stability Control

#### SEATS

Reclining/Lounge Seats

#### WHEELS

Styled Steel Wheels

#### PAINT

Clear Coat Paint

#### TRUCK

Rear Step Bumper

Get live updates at [www.carwise.com/e/5ahxyS](http://www.carwise.com/e/5ahxyS)

## Preliminary Estimate

**Customer: SLC Mosquito Abatement**

**Job Number:**

2011 CHEV Silverado 2500 HD Work Truck Regular Cab 133.7" WB 4WD 2D P/U 8-6.0L Gasoline SFI White

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		<b>PICK UP BOX</b>					
2	*	Rpr RT Outer panel Chevrolet				16.0	3.3
3		Add for Clear Coat					1.3
4	*	Rpr LT Outer panel Chevrolet				7.0	3.3
5		Overlap Major Non-Adj. Panel					-0.2
6		Add for Clear Coat					0.6
7		R&I R&I tailgate assy				0.3	
8		Repl RT Decal "4x4"	25798301	1	111.54	0.3	
9		Repl LT Decal "4x4"	25798301	1	111.54	0.3	
10		Repl RT Stone guard front-w/o dual rr wheels Chevrolet	15952192	1	40.90	0.2	
11	*	Rpr RT Rear pillar				1.0	0.5
12		<b>REAR BUMPER</b>					
13	**	Repl A/M CAPA Bumper assy w/o dual rr wheels w/o park sensor	22932801	1	912.00	1.1	
14		<b>REAR LAMPS</b>					
15	*	Repl LKQ RT Combo lamp assy Chevrolet +25%	20840272	1	68.75	0.3	
16		<b>MISCELLANEOUS OPERATIONS</b>					
17	*	Repl Cover car/bag		1	8.00	0.2	
18	#	Subl Hazardous waste removal		1	5.00 T		
19	#	Repl Corrosion protection primer		1	T		0.5
20	#	R&I Tool Box				1.0	
<b>SUBTOTALS</b>					<b>1,257.73</b>	<b>27.7</b>	<b>9.3</b>

### ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			1,252.73
Body Labor	27.7 hrs @	\$ 62.00 /hr	1,717.40
Paint Labor	9.3 hrs @	\$ 62.00 /hr	576.60
Paint Supplies	9.3 hrs @	\$ 42.00 /hr	390.60
Miscellaneous			5.00
Subtotal			3,942.33
<b>Grand Total</b>			<b>3,942.33</b>
Deductible			0.00
<b>CUSTOMER PAY</b>			<b>0.00</b>
<b>INSURANCE PAY</b>			<b>3,942.33</b>

**MyPriceLink Estimate ID / Quote ID:**

1389991744002596864 / 147448219

## Preliminary Estimate

---

**Customer: SLC Mosquito Abatement**

**Job Number:**

2011 CHEV Silverado 2500 HD Work Truck Regular Cab 133.7" WB 4WD 2D P/U 8-6.0L Gasoline SFI White

This is an Estimate only, some vehicles may require a tear down before the total cost of repairs will be known.

Bountiful Collision offers a limited lifetime warranty on work performed in our shop. Work performed on a sublet basis will be subject to the warranty of the repair facility performing the work. Parts are subject to the warranty of the manufacturer. In some cases, the insurer may offer an extended warranty, please check with your insurance company for information.

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

**Customer: SLC Mosquito Abatement**

**Job Number:**

2011 CHEV Silverado 2500 HD Work Truck Regular Cab 133.7" WB 4WD 2D P/U 8-6.0L Gasoline SFI White

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR1GH11, CCC Data Date 08/15/2025, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

**SYMBOLS FOLLOWING PART PRICE:**

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

**SYMBOLS FOLLOWING LABOR:**

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

**OTHER SYMBOLS AND ABBREVIATIONS:**

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

## Preliminary Estimate

**Customer: SLC Mosquito Abatement**

**Job Number:**

2011 CHEV Silverado 2500 HD Work Truck Regular Cab 133.7" WB 4WD 2D P/U 8-6.0L Gasoline SFI White

### PARTS SUPPLIER LIST

Line	Supplier	Description	Price
13	Keystone, Inc 3455 W NINIGRET DR SALT LAKE CITY UT 84104 (801) 886-1470	#GM1103164DSC A/M CAPA Bumper assy w/o dual rr wheels w/o park sensor Quote: 3112993665 Expires: 10/11/25	\$ 912.00
15	ALL TRUCK INC. 3380 SOUTH 500 WEST SALT LAKE CITY UT 84115 (801) 265-9800	#B2516 LKQ RT Combo lamp assy Chevrolet +25% RT TAIL LAMP Quote: CCC-319395960 Expires: 09/06/25	\$ 55.00

## Preliminary Estimate

**Customer: SLC Mosquito Abatement**

**Job Number:**

2011 CHEV Silverado 2500 HD Work Truck Regular Cab 133.7" WB 4WD 2D P/U 8-6.0L Gasoline SFI White

### ALTERNATE PARTS USAGE

2011 CHEV Silverado 2500 HD Work Truck Regular Cab 133.7" WB 4WD 2D P/U 8-6.0L Gasoline SFI White

VIN: 1GC0KVCG0BF160380	Interior Color:	Mileage In:	Vehicle Out:
License: 508831EX	Exterior Color: White	Mileage Out:	
State: UT	Production Date: 11/2010	Condition:	Job #:

Alternate Part Type	Selection Method	# Of Times Notified Of Available Parts	# Of Parts Selected
Aftermarket	Automatically List	1	1
Optional OEM	Manually List	0	0
Reconditioned	Automatically List	0	0
Recycled	N/A	1	1